

NOTES

- EROSION 6-8 FEET HIGH.
- SEVERE EROSION UP TO 30-FEET HIGH AT BEND AND OUTFALL UNDERCUT.
- EROSION UP TO 12-FEET HIGH. WEATHERED SHALE AT BASE, NORTH SIDE.
- CONCRETE ENCASED UTILITY CROSSING.
- EROSION OF BOULDER FILL AT BEND.
- PAST EROSION PROBLEMS, SOME CURRENT SOIL SLUMPING.
- ERODING BANK, FENCE UNDERMINED ON SOUTH SIDE.

NOTES

- SIDE BANK SEEPAGE, NORTH SIDE.
- SHORT WALL BEING UNDERMINED AT CURVE, NORTH SIDE.
- SMALL OUT CROP OF WEATHERED SHALE, SOUTH SIDE.

GENERAL NOTES

ENTIRE REACH HAS BEEN CHANNELIZED, FILLED AND ALTERED. NO NATURAL STRETCH EXISTS. EROSION ALONG BOTH BANKS IS COMMON. CHANNEL BOTTOM IS MAINLY FINE TO COARSE SAND WITH SCATTERED GRAVEL AND COBBLES. SOME DEBRIS ALSO PRESENT.

SIDE BANKS ARE VARIABLE AND CONSIST OF DEBRIS/FILL; GRAVELLY CLAY; AND SAND AND GRAVEL.

FIGURE 3.5-1

GEOLOGIC MAP

LEGEND

RECENT ALLUVIUM

LANDFILL

Qal

KNOWN OR SUSPECTED SOLID WASTE

MAN PLACED FILL (ONLY MAPPED LOCALLY)

PINEY CREEK ALLUVIUM (LOW TERRACE)

MULLER ENGINEERING CO., INC.

CONSULTING ENGINEERS

550 SOUTH WADSWORTH BLVD. SUITE 500
LAKEWOOD, COLORADO 80226-3118
(303) 937-3500 CTL. Thompson



FOUNTAIN CREEK DRAINAGE BASIN PLANNING STUDY

CITY OF COLORADO SPRINGS PLANNING, DEVELOPMENT AND FINANCE DEPARTMENT

GEOMORPHOLOGY AND GEOLOGIC RESOURCES

SHEET 4 OF 4